713 6449 90 SCHAEFFLER FAG Łożysko koła SCHAEFFLER FAG 713 6449 90

Image not found or type unknown

Łożysko koła SCHAEFFLER FAG 713 6449 90

Producent: SCHAEFFLER FAG

Kod produktu: 713 6449 90

Jednostka: szt.

Cena: 342 zł z VAT/szt.

Cena i dostępność może ulec zmianie

Sprawdź aktualną cenę online »

Image not found or type unknown

Specyfikacja części

Łożysko koła SCHAEFFLER FAG 713 6449 90 (713 6449 90), firmy **SCHAEFFLER FAG**

Informacje

- **Odpowiada zakresowi dostawy**
- Adnotacja uzupełniająca: **Fotografia**
- Średnica zewnętrzna 2 [mm]: **67,80**
- Szerokość 2 [mm]: **42,10**
- Średnica zewnętrzna [mm]: **156,70**
- Średnica zewnętrzna 1 [mm]: **91,20**
- **Pierścień czujnika ABS**
- Adnotacja uzupełniająca 2: **Z**

Opinie o produkcie

Image not found or type unknown

Sprawdź opinie o części innych klientów

Montowane w autach

Niniejszy PDF nie stanowi obowiązującej oferty

Copyright © Sp. z o.o.
Wszelkie prawa zastrzeżone

713 6449 90 SCHAEFFLER FAG Łożysko koła SCHAEFFLER FAG 713 6449 90

Opel	INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A Country Tourer (G09) , INSIGNIA A Country Tourer (G09) , INSIGNIA A Country Tourer (G09) , INSIGNIA A Country Tourer (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A sedan (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Sports Tourer (G09) , INSIGNIA A Country Tourer (G09) , INSIGNIA A Country Tourer (G09) , INSIGNIA A Country Tourer (G09)
Saab	9-5 (YS3G) , 9-5 (YS3G) , 9-5 (YS3G) , 9-5 (YS3G) , 9-5 (YS3G)

Sprawdź szczegóły

Numery OEN

FEBI	39916
MOOG	OP-WB-11083 , OPWB11083
OPEL	13507374 , 3 28 042 , 3 28 292 , 328042 , 328292
OPTIMAL	202300
RUV	5368
SCHAEFFLER	713 6449 90 , 713644990
SKF	VKBA 7009 , VKBA7009
SNR	R153.63 , R15363
VAUXH	3 28 292 , 328292

Sprawdź szczegóły

Niniejszy PDF nie stanowi obowiązującej oferty

Copyright © Sp. z o.o.
Wszelkie prawa zastrzeżone