



image not found or type unknown

Sklep z częściami samochodowymi nr 1



image not found or type unknown
22 884 65 45



image not found or type unknown
bok@iparts.pl

20L9010-JPN JPN Łożysko koła JPN 20L9010-JPN



Łożysko koła JPN 20L9010-JPN

Producent: JPN

Kod produktu: 20L9010-JPN

Jednostka: szt.

Cena: **105** zł z VAT/szt.

Cena i dostępność może ulec zmianie

[Sprawdź aktualną cenę online »](#)



image not found or type unknown

Specyfikacja części

Łożysko koła JPN 20L9010-JPN (20L9010-JPN), firmy **JPN**

Informacje

- Lokalizacja w aucie: **Oś tylna**
- Szerokość [mm]: **61,50**
- Średnica wewnętrzna [mm]: **30,00**
- Średnica zewnętrzna [mm]: **120,00**

Opinie o produkcie



image not found or type unknown

[Sprawdź opinie o części innych klientów](#)

Montowane w autach

Audi

A3 (8L1) , A3 (8L1) , A3 (8L1) , TT (8N3) , TT Roadster (8N9) , TT Roadster (8N9) , TT Roadster (8N9) , A3 (8L1) , A3 (8L1) , A3 (8L1) , TT Roadster (8N9) , TT (8N3) , TT (8N3) , TT (8N3) , A3 (8L1) , A3 (8L1) , A3 (8L1)

Niniejszy PDF nie stanowi obowiązującej oferty

Sklep internetowy iParts.pl

Sprzedaż części i infolinia:
22 884 65 45

e-mail: handlowy@iparts.pl

Dane spółki

iParto Sp.z o.o.
ul. Szeligowska 48B,
05-850 Szeligi
Warszawa Bemowo
NIP: 5242878832
Regon: 382151711

www.iparts.pl

Copyright © Sp. z o.o.
Wszelkie prawa zastrzeżone

**20L9010-JPN JPN** Łożysko koła JPN 20L9010-JPN

Montowane w autach

Seat	LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), TOLEDO II (1M2), TOLEDO II (1M2), TOLEDO II (1M2), TOLEDO II (1M2), TOLEDO II (1M2), TOLEDO II (1M2), TOLEDO II (1M2), LEON (1M1), LEON (1M1), LEON (1M1), LEON (1M1), TOLEDO II (1M2), TOLEDO II (1M2), TOLEDO II (1M2), TOLEDO II (1M2)
Skoda	OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER Praktik (5J), ROOMSTER Praktik (5J), ROOMSTER Praktik (5J), OCTAVIA I (1U2), ROOMSTER (5J7), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I (1U2), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), OCTAVIA I Combi (1U5), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER (5J7), ROOMSTER Praktik (5J), ROOMSTER Praktik (5J), ROOMSTER Praktik (5J), ROOMSTER Praktik (5J)
Vw	BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), NEW BEETLE kabriolet (1Y7), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA I (1J2), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), BORA Variant (1J6), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE (9C1, 1C1), NEW BEETLE kabriolet (1Y7), NEW BEETLE kabriolet (1Y7), NEW BEETLE kabriolet (1Y7), NEW BEETLE kabriolet (1Y7), NEW BEETLE kabriolet (1Y7), NEW BEETLE kabriolet (1Y7), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV (1J1), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5), GOLF IV Variant (1J5)
Sprawdź szczegóły	

Numery OEM

AUDI	1J0 501 477 A, 1J0 598 477, 1J0501477A, 1J0598477
FAG	713 6102 20
FEBI	09521, 24236
HART	901 071, 921 415
IPD	30-1022, 301022
JPN	20L9010-JPN

Niniejszy PDF nie stanowi obowiązującej oferty

Sklep internetowy iParts.pl

Dane spółki

www.iparts.pl

Sprzedaż części i infolinia:
22 884 65 45e-mail: handlowy@iparts.pliParto Sp. z o.o.
ul. Szeligowska 48B,
05-850 Szeligi
Warszawa Bemowo
NIP: 5242878832
Regon: 382151711Copyright © Sp. z o.o.
Wszelkie prawa zastrzeżone

**20L9010-JPN JPN** Łożysko koła JPN 20L9010-JPN

Numery OEN	
Omnicaft	2466376 , KAMJ-1A049-ABAA , KAMJ1A049ABAA
QUINTON HA	QWB1055
RIDEX	654W0017
RUV	5720
SEAT	1J0 501 477 A , 1J0 598 477 , 1J0501477A , 1J0598477
SKF	BR9318 , VKBA 3456 , VKBA3456
SKODA	1J0 501 477 A , 1J0 598 477 , 1J0501477A , 1J0598477
SNR	R157.20 , R15720
SPIDAN	0.027111 , 0027111
TRIPLEFIVE	327 1300 , 3271300 , 416.03.13 , 416.06.10 , 4160313 , 4160610 , FD015051A0
VAICO	V10-0046
VW FAW	L 1J0 501 477 A , L1J0501477A
VW	180 501 477 , 180501477 , 1J0 501 477 A , 1J0 501 611 D , 1J0 598 477 , 1J0501477A , 1J0501611D , 1J0598477
Sprawdź szczegóły	

Niniejszy PDF nie stanowi obowiązującej oferty

Sklep internetowy iParts.pl

Sprzedaż części i infolinia:
22 884 65 45e-mail: handlowy@iparts.pl

Dane spółki

iParto Sp.z o.o.
ul. Szeligowska 48B,
05-850 Szeligi
Warszawa Bemowo
NIP: 5242878832
Regon: 382151711www.iparts.plCopyright © Sp. z o.o.
Wszelkie prawa zastrzeżone