

302408 VALEO Klocki hamulcowe - komplet VALEO 302408



Klocki hamulcowe - komplet VALEO 302408

Producent: VALEO

Kod produktu: 302408

Jednostka: szt.

Cena: **84** zł z VAT/szt.

Cena i dostępność może ulec zmianie

[Sprawdź aktualną cenę online »](#)

Kup część

Specyfikacja części

Klocki hamulcowe - komplet VALEO 302408 (302408), firmy VALEO

Informacje

- Lokalizacja w aucie: **Oś tylna**
- Szerokość [mm]: **93**
- Grubość [mm]: **16**
- Styk ostrzegawczy o zużyciu: **Ze stykiem zużycia**
- Wytykujący / informacja uzupełniająca 2: **Z podkładką**
- System hamulcowy: **MANDO**
- Wysokość [mm]: **41**
- Numer WVA: **24320**
- Tryb pracy: **Mechaniczne**
- Rozrządzenie kontrolne: **ECE-**

Opinie o produkcie



[Sprawdź opinie o części innych klientów](#)

Montowane w autach

Niniejszy PDF nie stanowi obowiązującej oferty

Sklep internetowy iParts.pl

Sprzedaż części i infolinia:
22 884 65 45

e-mail: handlowy@iparts.pl

Dane spółki

iParto Sp. z o.o.
ul. Szeligowska 48B,
05-850 Szeligi
Warszawa Bemowo
NIP: 5242878832
Regon: 382151711

www.iparts.pl

Copyright © Sp. z o.o.
Wszelkie prawa zastrzeżone

302408 VALEO Klocki hamulcowe - komplet VALEO 302408

Hyundai	i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i20 I (PB, PBT) , i20 I (PB, PBT) , i20 I (PB, PBT) , i20 I (PB, PBT) , i20 I (PB, PBT) , ix35 (LM, EL, ELH) , ACCENT III (MC) , ACCENT III (MC) , i30 (FD) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix20 (JC) , ix20 (JC) , i30 (GD) , ACCENT III sedan (MC) , ACCENT III (MC) , SONATA VI (YF) , SONATA V (NF) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix35 (LM, EL, ELH) , ix20 (JC) , ix20 (JC) , ix20 (JC) , i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i30 Kombi (FD) , i20 I (PB, PBT) , i20 I (PB, PBT) , ACCENT III sedan (MC) , ACCENT III sedan (MC)
Kia	CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , CERATO II sedan (TD) , CERATO II sedan (TD) , SPORTAGE II (JE_ , KM) , SPORTAGE II (JE_ , KM) , SPORTAGE II (JE_ , KM) , SPORTAGE II (JE_ , KM) , RIO II sedan (JB) , RIO II sedan (JB) , RIO II sedan (JB) , RIO II (JB) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D liftback (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , CEE'D SW (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , PRO CEE'D (ED) , CERATO II sedan (TD) , SPORTAGE II (JE_ , KM) , SPORTAGE II (JE_ , KM) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , SPORTAGE III (SL) , RIO II (JB) , RIO II (JB) , RIO II (JB)
Sprawdź szczegóły	

Numery OEM	
ATE	13.0460-5780.2 , 13046057802
BENDIX	DB1943
BOSCH	0 986 494 140 , 986494140
BREMBO	P 30 025 , P30025
COMLINE	ADB31543 , ADB32016 , ADB32276 , CBP31543 , CBP32016 , CBP32276
DELPHI	LP1952
FEBI	116260 , 116270 , 222367
FERODO	FDB1956 , FDB4235G , FDB4235W , FDB4408W
FTE	9010572

Niniejszy PDF nie stanowi obowiązującej oferty

Sklep internetowy iParts.pl

Dane spółki

www.iparts.pl

Sprzedaż części i infolinia:
22 884 65 45

e-mail: handlowy@iparts.pl

iParto Sp.z o.o.
ul. Szeligowska 48B,
05-850 Szeligi
Warszawa Bemowo
NIP: 5242878832
Regon: 382151711

Copyright © Sp. z o.o.
Wszelkie prawa zastrzeżone

302408 VALEO Klocki hamulcowe - komplet VALEO 302408

Numery OEN	
HYUNDAI BJ	58302-1GA00 , 583021GA00
HYUNDAI	58302-1GA00 , 58302-1HA10 , 58302-1JA30 , 58302-1KA30 , 58302-2SA10 , 58302-2SA30 , 58302-2SA70 , 58302-2YA31 , 58302-2YA50 , 58302-3SA20 , 583021GA00 , 583021HA10 , 583021JA30 , 583021KA30 , 583022SA10 , 583022SA30 , 583022SA70 , 583022YA31 , 583022YA50 , 583022YA70 , 583023SA20 , S58302 1GA00 , S58302-2SA30 , S583021GA00 , S583022SA30
ICER	181712
KIA DYK	583021GA00
KIA	58302-0ZA00 , 58302-1GA00 , 58302-1HA00 , 58302-1MA40 , 58302-2SA10 , 58302-2SA30 , 58302-2SA70 , 58302-2YA31 , 58302-2YA50 , 583020ZA00 , 583021GA00 , 583021HA00 , 583021MA40 , 583022SA10 , 583022SA30 , 583022SA70 , 583022YA31 , 583022YA50 , S58302-2SA30 , S583020ZA00 , S583022SA30
LPR	05P2103 , 5P2103
MIN	MDB2734
NK	223521
RAICAM	RA.0979.0 , RA.0979.1 , RA.0979.1K1 , RA.0979.2 , RA.0979.2K1 , RA09790 , RA09791 , RA09791K1 , RA09792 , RA09792K1
ROULUNDS	847881
SANGSIN BR	SP1187
SASIC	6216097
STARLINE	BD S409P , BD S627P , BD S630P , BD S636P , BD S639P , BDS409P , BDS627P , BDS630P , BDS636P , BDS639P
TRW	GDB3421
VALEO	598867
Sprawdź szczegóły	

Niniejszy PDF nie stanowi obowiązującej oferty

Sklep internetowy iParts.pl

Sprzedaż części i infolinia:
22 884 65 45

e-mail: handlowy@iparts.pl

Dane spółki

iParto Sp. z o.o.
ul. Szeligowska 48B,
05-850 Szeligi
Warszawa Bemowo
NIP: 5242878832
Regon: 382151711

www.iparts.pl

Copyright © Sp. z o.o.
Wszelkie prawa zastrzeżone